

Draft
Maintenance Concept Remains Consistent with Prior Fiscal Year

STATEMENT OF WORK (SOW)
REBUILD OF
MORTAR, 81-MM: M252
NSN 1015-01-164-6651

1.0 Scope. This Statement of Work (SOW) establishes and sets forth task, and identifies the work effort that shall be performed by the contractor in the Rebuild effort of the Mortar, 81-MM: M252, ID# 09922A, TAMCN E1095, NSN 1015-01-164-6651 (hereafter known as the M252 Mortar, 81 MM). This document contains requirements to restore the M252 Mortar, 81 MM to Condition Code "A." Condition Code A is defined as "serviceable/issuable without qualification, new, used, repaired or reconditioned material which is serviceable and issuable to all customers without limitation or restriction. This includes material with more than six months shelf life remaining.

1.1 Background. Rebuild is defined as "That maintenance technique to restore an item to a standard as near as possible to the original or new condition in appearance, performance, and life expectancy." This is accomplished through a maintenance technique or complete disassembly of the item, inspection of all parts or components, repair or replacement of worn or unserviceable elements using original manufacturing tolerances and/or specifications and subsequent reassembly of the item.

2.0 Applicable Documents. The following documents form a part of this SOW to the extent specified. Unless otherwise specified, the issues of these documents are those listed in the Department of Defense Index of Specifications and Standards (DoDISS) and supplement thereto which is in effect on the date of solicitation. In the event of conflict between the documents referenced herein and the contents of this SOW, the contents of this SOW shall be the superseding requirement.

2.1 Military Standards

MIL-STD-129

DoD Standard Practice for Military Marking

2.2 Other Government Documents and Publications

AM11579801

Special Packaging Instructions

DMWR 9-1015-249

Depot Maintenance Work Requirement dtd 21 Apr 89

RS 09922A-50

Rebuild Standard 09922A-50 w/changes 1&2

DoD 4000.25-1-M

Military Standard Requisitioning and Issue
Procedures (MILSTRIP)Military Handbook (For Guidance Only)

MIL-HDBK-61

Configuration Management Guidance

2.3 Industry Standards

ANSI/ISO/ASQC Q9001-2000

Quality Management Systems-Requirements

Industry Standards (For Guidance Only)

ANSI/EIA-649

National Consensus Standard for Configuration
Management

Copies of Military Specifications and Standards are available from the DoD Single Stock Point, Document Automation and Production Service, Building 4/D, 700 Robbins Avenue, Philadelphia, PA 19111-5094, commercial telephone number (215) 697-2179 or DSN 442-2179, or <http://www.dodssp.daps.mil>. Copies of other government documents or publications required by the contractor in connection with specific statement of work requirements shall be obtained through the Contracting Officer: Contracts Department (Code 891), P.O. Drawer 43019, 814 Radford Blvd., Marine Corps Logistics Bases, Albany, Georgia, 31704-3019, commercial telephone number (229) 639-6761 or DSN 567-6761. Copies of engineering drawings, if applicable, shall be obtained from Marine Corps Systems Command (Code IWS), 814 Radford Blvd., Suite 20343, Albany, Georgia 31704-0343, commercial telephone number (229) 639-5083 or DSN 567-5083.

3.0 Requirements

3.1 Rebuild. The contractor shall rebuild the M252 Mortar, 81 MM in accordance with DMWR 9-1015-249 and RS 09922A-50.

3.2 Quality Assurance/Quality Control. The Contractor shall provide and maintain a Quality System that as a minimum, adheres to the requirements of ANSI/ISO/ASQC Q9001-2000, Quality Management Systems - Requirements and shall be in accordance with DMWR 9-1015-249, Chapter 5.

3.3 Configuration Control. The contractor shall apply configuration control procedures to establish configuration items. The contractor shall not implement configuration changes to an item's documented performance or design characteristics without prior written authorization. If it is necessary to temporarily depart from the authorized configuration, the contractor shall prepare and submit a Request For Deviation. MIL-HDBK-61 and ANSI/EIA-649 provide guidance for preparing this configuration control document.

3.4 Packaging, Handling, Storage and Transportation (PHS&T).

a. The Contractor shall be responsible for the preservation and packaging of item(s) being repaired under the terms of this statement of work. Items scheduled for long-term storage or shipment to overseas destinations shall be in accordance with level "A" requirements of Special Packaging Instruction (SPI) AM11579801, which may be obtained from the Storage & Distribution Department (Code 580), Business Management Branch (Code 581), 814 Radford Blvd., Suite 20320, Albany, Georgia 31704-0320, commercial telephone number (229) 639-6786 or DSN 567-6786. Items scheduled for domestic shipment for immediate use shall be in accordance with level "B" requirements.

b. Marking for shipment and storage shall be in accordance with MIL-STD-129.

c. The Marine Corps will provide the contractor with shipping address(es) for delivery of the repaired equipment. The Contractor shall be responsible for arranging shipment to the pre-designated site(s). The Marine Corps will be responsible for transportation cost associated with shipping the subject equipment to and from the contractor.

3.5 Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM). The Management Control Activity (MCA/Code 573-2) will coordinate Government Furnished Equipment/Government Furnished Materiel (GFE/GFM) request and maintain a central control system on all government owned assets in the contractor's possession. The MCA will forward a GFE Accountability Agreement to the contractor for signature on an annual basis to establish a chain of custody and identify property responsibilities for Marine Corps assets. The contractor is to acknowledge receipt of GFM to the MCA within 15 days of receipt. This can be done by mailing a copy of the DD1348 to Materiel Management Department, Management Control Activity (Code 573-2), 814 Radford Blvd., STE 20320, Albany, Georgia, 31704-0320 or faxing a copy to commercial phone number (229) 639-5498 or DSN 567-5498.

3.6 Contractor Furnished Materiel (CFM). The contractor may requisition materiel as required in the performance of the statement of work through the DOD Supply System. DOD 4000.25-1-M, (MILSTRIP) Chapter 11 provides guidance to the contractors on the requisition process. The contractor's decision to utilize CFM procured from the DoD Supply System shall be based upon cost effectiveness, availability of materiel and the required completion/delivery date.

4.0 REPORTS

4.1 Monthly Progress Reports. The Contractor shall provide Monthly Progress Reports summarizing the progress status of the Rebuild Program to Marine Corps Systems Command, (Code IWS), 814 Radford Blvd., Suite 20343, Albany, Georgia 31704-0343.